


## FAQ #6: How do I verify my toolpath?

Before simulating any cutting features, the tool paths must first be calculated using either **Compute** under each feature or by selecting **Compute All Toolpath** under the right-click menu for **CAM Part**.

**Step 1.** To simulate a machine running a program, right-click on either **Milling Stock** or **Turning Stock** in the **Cam Tree** tab of the **Data-CAM Tree Manager**. Choose **Verify** from the list. The simulation window will immediately appear with a block the size of the part in it.



**Step 2.** To start the simulation running, simply click on the **Start** button.

